Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)



Partia	Complete XXX Exploration
Inspection Date: 0	3/15/2002 / Time: 10:30am-2:30pm
-	Date of Last Inspection: 2/15/2002

Ine Name: Wellington Prep Plant County: Carbon Permit Number: C/007/012							
Permittee and/or Operator's Name: Nevada Electric Investment Company (NEICO)							
Business Address: c/o Mt. Nebo Scientific, P.O. Box 337, Springville, Utah 84663							
ompany Official(s): Patrick Collins							
State Official(s): Stephen J. Demczak Federal Official(s): None							
Veather Conditions: Cold, 30's, clear skies							
Type of Mining Activity: Underground Surface Prep Plant XXX Other							
Existing Acreage: Permitted 1573.5 Disturbed 392 Regraded Seeded							
tatus: Active							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- . Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]			\Box
3.	TOPSOIL	[X]	\Box	[X]	\Box
4.	HYDROLOGIC BALANCE:	. ——			
a.	DIVERSIONS	[X]	\Box	[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	\Box
d.	WATER MONITORING	$\overline{[X]}$	\Box	[X]	$\overline{\square}$
e.	EFFLUENT LIMITATIONS	$\overline{[X]}$	$\overline{\Box}$	[X]	$\overline{\square}$
5.	EXPLOSIVES		[X]		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]		\Box	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<u>[X]</u>		[X]	П
8.	NONCOAL WASTE	[X]	[]	[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]	Ш		\Box
10.	SLIDES AND OTHER DAMAGE	$\overline{[X]}$		\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	[X]	$\overline{\square}$		\Box
12.	BACKFILLING AND GRADING	[X]	$\overline{\square}$	$\overline{\square}$	Ш
13.	REVEGETATION	$\overline{[X]}$			
14.	SUBSIDENCE CONTROL		$\overline{[X]}$		
15.	CESSATION OF OPERATIONS	[X]	$\overline{\square}$		
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]		\Box	\Box
b.	DRAINAGE CONTROLS	<u>[X]</u>			\Box
17.	OTHER TRANSPORTATION FACILITIES	<u>[X]</u>			\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	<u>[X]</u>	[]	[X]	\Box
19.	AVS CHECK (4th Quarter- April, May, June)	[X]		[.]	\Box
20.	AIR QUALITY PERMIT	<u>[X]</u>			\Box
21.	BONDING & INSURANCE	[X]	[]	[X]	

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/007/012

DATE OF INSPECTION: 03/15/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

No new amendments have been sent to the Division by the permittee.

2. SIGNS AND MARKERS

Spot-checks of the disturbed area markers were made throughout the property. The permittee was in compliance.

3. TOPSOIL

The topsoil piles were inspected and there were no signs of wind or water erosion. The topsoil piles are surrounded by berms.

The permittee is in the process of removing the slurry pipeline bridge. The Division has given an approval for this project. A welding torch was used to remove welds, bolts, nuts, and rivets from the bridge before the structure can be removed. During this process, hot molten metal caught the nearby grasses on fire. The grass fire was within the permit area, burning approximately 5 to 10 acres. This action should not cause damage to the grasses. This is a common practice in this area to burn fields and lawns to stimulate the vegetation.

Patrick Collins, resident agent, has committed to reseed the area in the late fall if the vegetation does not fully recover.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked and were found to comply with the requirements of the Mining and Reclamation Plan and the R645 Coal Rules. The undisturbed diversion located above the Westside property will need to be cleaned out in the near future.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were not discharging during the inspection and are not likely to discharge in the near future. These ponds did contain a little or no water. There were no signs of any hazardous conditions during the inspection. The sediment ponds were inspected on December 21, 2001. The inspections are P.E. certified by Dan Guy. The fourth quarter report will also be used as the annual sediment pond inspection.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Siltation structures were inspected and complied the R645 Coal Rules. The permittee uses straw bales and silt fences in the disturbed area.

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/007/012

DATE OF INSPECTION: 03/15/2002

4D. HYDROLOGIC BALANCE: WATER MONITORING

Fourth quarter water monitoring was reviewed. It consisted of checking parameters, sampling at required site locations, and holding time requirements for water samples. No problems were found with the requirements in the R645 Coal Rules and the MRP. The permittee has submitted all information for fourth quarter into the water electronic database system except for the UPDES water sample sites. This was confirmed by the inspector checking the water database. The permittee will begin to submit the UPDES water information beginning the second quarter.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

There were no discharges for the fourth quarter.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse piles were inspected on December 21, 2001. This report is P.E. certified. No hazardous conditions were reported.

8. NONCOAL WASTE

The area was clear of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new support facilities were built since the last inspection.

20. AIR QUALITY PERMIT

The permittee is in compliance with the air quality permit. There are two Air Quality permits for Wellington Prep. Plant. The east side of the Price River has a separate permit (DAQE-1014-97) and west side of the Price River has a permit (DAQE-997-92).

21. BONDING AND INSURANCE

The permit area is 1573.5 acres and the disturbed area is 392 acres. Exhibit "A" states that the bonded area equals the permit area. The bonding is set at \$4,904,000.

The insurance policy was inspected and complies with the coal rules. The policy covers explosives. The insurance will expire on February 9, 2003. The insurance is being carried by Scottsdale Insurance Co.

Inspector's Signature:

Stephen J. Demozak

Date: March 18, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Patrick Collins, Mt. Nebo for NEICO

Price Field office

O:\007012.WEL\Compliance\2002\c 0315.doc